



CAIXAS DE SATÉLITES PARA MERCEDES, SCANIA E VOLVO



MERITOR



Caixas de Satélites para Mercedes, Scania e Volvo

Código Meritor	Nº Original	Eixo	Aplicação
808209	1315202	R780	SCANIA G/P/R/T93; P/R/T113; R/T143; 94C/D/G/L; 114C/G/L; 124C/G/L; 144C/G/L; 164C/G/L; P/R380; P/R420; P/R480; P/R500; P/R560; P/R620
808210	1677420 1308616	R780	SCANIA G/P/R/T93; P/R/T113; R/T143; 94C/D/G/L; 114C/G/L; 124C/G/L; 144C/G/L; 164C/G/L; P/R380; P/R420; P/R480; P/R500; P/R560; P/R620
808211	1116697	R770	SCANIA G82; P82; G92; P92; R92; G112; P112; R112; T112; R142; T142; G93; P93; R93; T93; P113; R113; T143
808212	1522290	EV81B / EV81C / EV87	VOLVO F10; F12; F16; FH12; FH16; FL7; FL10; FM7; FM9; FM10; FM12; F88; G88; N10; N12; N88; NH12; NL10; NL12
808213	1522133	EV81B / EV81C / EV87 / EV80 EV80B / EV82 / EV82B	VOLVO B58; F10; F12; F16; FH12; FH16; FL7; FL10; FM7; FM9; FM10; FM12; F88; F89; FB88; G88; G89; N10; N12; N88; NH12; NL10; NL12; B7; B10B; B9M; B10M; FL616; FL619
808214	333541	R641 / R642 / R750 R751 / R752 / R770	SCANIA G82; P82; G92; P92; R92; G112; P112; R112; T112; R142; T142; G93; P93; R93; T93; P113; R113; T113; R143; T143 LB81 (H); LB/S/T86 (H); LB/S/T111 (H); LB/S/T140 (H); LB/S/T141 (H); LT146
808215	1116696	R770	SCANIA G82; P82; G92; P92; R92; G112; P112; R112; T112; R142; T142; G93; P93; R93; T93; P113; R113; T113; R143; T143
808216	1677421 1344188	R780	SCANIA G/P/R/T93; P/R/T113; R/T143; 94C/D/G/L; 114C/G/L; 124C/G/L; 144C/G/L; 164C/G/L; P/R380; P/R420; P/R480; P/R500; P/R560; P/R620
808217	3463502127 21350030	HL7	MBB 1630; 1634; 1929; 1932; 1933; 1934; 1935; 1938; 1941; LS1933; LS1935 redução 26X24
808218	294856	R70 / R751 / R752	SCANIA LB81 (H); LB/S/T86 (H); LB/S/T111 (H); LB/S/T140 (H); LB/S/T141 (H); LT146; G112; P112; R112; T142; R142; T142
808219	3463501127 21350025	HL7 / HD7	MBB 1630; 1634; 1929; 1932; 1933; 1934; 1935; 1938; 1941; 2635; 2638; L1929; L1932; L1934; LK1929; LK1932; LK1934; LS1929; LS1932; LS1934 redução 26X24; O371 UP; O400 UP
808220	1522289	EV81B / EV81C / EV87 / EV80 / EV80B / EV82 / EV82B	VOLVO B58; F10; F12; F16; FH12; FH16; FL7; FL10; FM7; FM9; FM10; FM12; F88; F89; FB88; G88; G89; N10; N12; N88; NH12; NL10; NL12; B7; B10B; B9M; B10M; FL616; FL619
808221	1377900 315978	RP830/831/832 RBP830/831/832	SCANIA LB/S/T111 (H); LB/LBS/LBT141 (H); LT146; G/P/R/T112; R/T142; P/R113; R/T143; 94C/D/G/L; 114C/G/L; 124C/G/L; 144C/G/L; 164C/G/L
808222	1377902 274099	RP830/831/832 RBP830/831/832	SCANIA LB/S/T111 (H); LB/LBS/LBT141 (H); LT146; G/P/R/T112; R/T142; P/R113; R/T143; 94C/D/G/L; 114C/G/L; 124C/G/L; 144C/G/L; 164C/G/L
808223	1368527	R560/660; RB660; RB662	SCANIA 94C/D/G/L; 114C/G/L; 124C/G/L; P340/380/420/480; R340/380/420/480 BUS K94/114CLB



Meritor do Brasil Sistemas Automotivos Ltda.
Rodovia Presidente Castelo Branco,
km 30,5 nº 11.250 - CEP 06421-400
Bairro dos Altos - Barueri/SP - Brasil

0800 55 5530
duvidas.tecnicas@meritor.com
reposicao.barueri@meritor.com
meritor.com/brasil
www.meritorpartsonline.com

© Meritor, Brazil.
Litho in Brazil,
Issued 08-12